


Client Report

Duration 25/07/2024 - 25/07/2024

Date	Ref #	Casa	Before	After	Extra	Length	Width	Area (m ²)
25/07/2024	0001	Kesrouane				0.70	2.00	1.40
25/07/2024	0002	Kesrouane				0.80	1.40	1.12
25/07/2024	0003	Kesrouane				1.30	2.70	3.51
25/07/2024	0004	Kesrouane				0.40	1.30	0.52
25/07/2024	0005	Kesrouane				0.70	1.30	0.91
25/07/2024	0006	Kesrouane				1.20	1.30	1.56
25/07/2024	0007	Kesrouane				1.20	2.30	2.76
25/07/2024	0008	Kesrouane				1.00	2.80	2.80

25/07/2024	0009	Kesrouane				1.90	2.50	4.75
25/07/2024	0010	Kesrouane				3.20	3.00	9.60
25/07/2024	0011	Kesrouane				1.40	1.80	2.52
25/07/2024	0012	Kesrouane				1.30	2.00	2.60
25/07/2024	0013	Kesrouane				1.00	3.10	3.10
25/07/2024	0014	Kesrouane				0.70	2.90	2.03
25/07/2024	0015	Kesrouane				1.40	5.70	7.98
25/07/2024	0016	Kesrouane				0.90	0.90	0.81
25/07/2024	0017	Kesrouane				1.50	1.70	2.55

25/07/2024	0018	Kesrouane				0.50	1.30	0.65
25/07/2024	0019	Kesrouane				0.40	1.00	0.40
25/07/2024	0020	Kesrouane				0.50	0.90	0.45
25/07/2024	0021	Kesrouane				0.80	1.00	0.80

Total (m ²)							52.82
Pothole Count							21