











Client Report

Duration 15/1/2025 - 15/1/2025

Date	Ref #	Casa	Before	After	Extra	Length	Width	Area (m ²)
15/01/2025	0001	Koura				0.40	8.00	3.20
15/01/2025	0002	Koura				1.00	2.00	2.00
15/01/2025	0003	Koura				1.10	1.10	1.21
15/01/2025	0004	Koura				1.20	2.80	3.36
15/01/2025	0005	Koura				1.00	2.40	2.40
15/01/2025	0006	Koura				0.30	0.30	0.09
15/01/2025	0007	Koura				0.50	0.50	0.25
15/01/2025	0008	Koura				0.30	0.30	0.09

15/01/2025	0009	Koura				0.50	1.50	0.75
15/01/2025	0010	Koura				0.90	1.60	1.44
15/01/2025	0011	Koura				1.00	1.00	1.00
15/01/2025	0012	Koura				1.30	2.60	3.38
15/01/2025	0013	Koura				1.00	1.00	1.00
15/01/2025	0014	Koura				1.00	1.20	1.20
15/01/2025	0015	Koura				1.00	1.60	1.60
15/01/2025	0016	Koura				1.10	1.40	1.54
15/01/2025	0017	Koura				2.00	2.00	4.00

29/01/2025 0018



6.00 6.00 36.00

Total (m ²)			64.51
Pothole Count			18